


GUILD OF CLEANERS
AND LAUNDERERS

56 Maple Drive, Larkhall,
South Lanarkshire,
ML9 2AR

Phone: 01698 322669
E-mail:
enquiries@gcl.org.uk

AMBER ALERT

Modacrylic Jacket Top Shop



Fabric Content

The outer fabric is 67% Modacrylic, 17% Polyester, 16% Acrylic Lining 100% Polyester,

Fabric Care Label

Gives all of the correct warnings and the Circle P underlined is also correct but the warning here is the treatment because Modacrylic is heat sensitive and in older machines without cool down you should beware that the item is taken out of the machine immediately the cycle is finished and do not use steam to finish



Problem is Top Shop Have More of These Shown Left is a Bomber Jacket and They are 100% Modacrylic

The outer shell is 100% Modacrylic and they are selling them in the sales reduced down to £35 from £75

Responsibility

For a damage caused is the cleaners responsibility because the warnings are all there in the care label.

Modacrylic can be dry-cleaned, however, they should not be steamed and should only be tumbled on cold. (cool drying).

Dynel and Verel are trade names for Modacrylic